

2125 Aldrich Pictures



Garage with bathroom/bedrooms



Boarded windows/transite siding



Living Room




Kitchen needs updating



Bathroom needs updating



Bathroom needs updating



Stairwell



Mechanicals require replacement



Upstairs



Upstairs water damage shown



Garage living space



Garage living space