

2200 Dupont Pictures



Stairway




Living Room




Living Room deteriorating paint



Kitchen needs updating



Bathroom needs updating



Bathroom needs updating



Bedroom



Bedroom water damage



Porch



3<sup>rd</sup> level



New Mechanicals required



Boiler suspect asbestos